

DIN EN 1948-1:2006-06 (E)

Stationary source emissions - Determination of the mass concentration of PCDDs/PCDFs and dioxin-like PCBs - Part 1: Sampling of PCDDs/PCDFs

Contents		Page
Foreword		3
Introduction		7
1 Scope		8
2 Normative references		8
3 Terms and definitions		9
4 Symbols and abbreviations		11
5 Principle of the complete PCDD/PCDF measurement procedure		12
6 Sampling device and materials		15
7 Minimum requirements for sampling		18
8 Safety measures and transport		21
9 Preparations and sampling		21
Annex A (informative) Toxicity and toxic equivalency		27
Annex B (informative) Examples of operation		30
Annex C (informative) Examples of adsorbents and their preparations and cleaning		58
Annex D (informative) Sampling measurement record		59
Annex E (informative) Relations to EU Directives		62
Bibliography		63