

# DIN EN ISO 277:2011-02 (E)

## Binders for paints and varnishes - Raw tung oil - Requirements and methods of test (ISO 277:2002)

---

<b>Contents</b>		<b>Page</b>
<b>Foreword</b> .....		<b>3</b>
<b>1</b>	<b>Scope</b> .....	<b>4</b>
<b>2</b>	<b>Normative references</b> .....	<b>4</b>
<b>3</b>	<b>Terms and definitions</b> .....	<b>5</b>
<b>4</b>	<b>Requirements and test methods</b> .....	<b>5</b>
<b>5</b>	<b>Methods of test</b> .....	<b>5</b>
<b>5.1</b>	<b>General</b> .....	<b>5</b>
<b>5.2</b>	<b>Sampling</b> .....	<b>5</b>
<b>5.3</b>	<b>Determination of gelation time</b> .....	<b>5</b>
<b>5.3.1</b>	<b>Apparatus</b> .....	<b>5</b>
<b>5.3.2</b>	<b>Preparation of sample</b> .....	<b>6</b>
<b>5.3.3</b>	<b>Procedure</b> .....	<b>6</b>
<b>5.4</b>	<b>Insoluble-bromide test</b> .....	<b>7</b>
<b>5.4.1</b>	<b>Reagents</b> .....	<b>7</b>
<b>5.4.2</b>	<b>Preparation of sample</b> .....	<b>7</b>
<b>5.4.3</b>	<b>Procedure</b> .....	<b>7</b>
<b>6</b>	<b>Typical values of fatty-acid contents</b> .....	<b>7</b>
<b>7</b>	<b>Test report</b> .....	<b>8</b>