

DIN EN ISO 277:2011-02 (E)

Binders for paints and varnishes - Raw tung oil - Requirements and methods of test (ISO 277:2002)

Contents		Page
Foreword		3
1	Scope	4
2	Normative references	4
3	Terms and definitions	5
4	Requirements and test methods	5
5	Methods of test	5
5.1	General	5
5.2	Sampling	5
5.3	Determination of gelation time	5
5.3.1	Apparatus	5
5.3.2	Preparation of sample	6
5.3.3	Procedure	6
5.4	Insoluble-bromide test	7
5.4.1	Reagents	7
5.4.2	Preparation of sample	7
5.4.3	Procedure	7
6	Typical values of fatty-acid contents	7
7	Test report	8