

DIN EN ISO 8502-6:2020-08 (E)

**Preparation of steel substrates before application of paints and related products -
Tests for the assessment of surface cleanliness - Part 6: Extraction of water soluble
contaminants for analysis (Bresle method) (ISO 8502-6:2020)**

Contents

	Page
European foreword	3
Foreword	4
Introduction	5
1 Scope	6
2 Normative references	6
3 Terms and definitions	6
4 Principle	7
5 Apparatus and materials	7
6 Procedure	8
6.1 Selection of test surface	8
6.2 Blank test	8
6.3 Extraction by patch or sleeve by injection	8
6.4 Extraction by sleeve by pre-filling	10
7 Analyses	10
8 Test report	10
Annex A (normative) Leak test for type testing of adhesive cells (patches and sleeves)	14
A.1 General	14
A.2 Principle	14
A.3 Apparatus and material	14
A.4 Procedure	14
A.5 Test report	15
Bibliography	16