

# DIN EN ISO 19403-2:2024-11 (E)

## Paints and varnishes - Wettability - Part 2: Determination of the surface free energy of solid surfaces by measuring the contact angle (ISO 19403-2:2024)

---

| <b>Contents</b>   | <b>Page</b> |
|---|-------------|
| European foreword .....   | 3           |
| Foreword .....  | 4           |
| <b>1 Scope</b> .....  | <b>5</b>    |
| <b>2 Normative references</b> .....   | <b>5</b>    |
| <b>3 Terms and definitions</b> .....  | <b>5</b>    |
| <b>4 Principle</b> .....  | <b>5</b>    |
| <b>5 Apparatus and materials</b> .....  | <b>6</b>    |
| <b>6 Sampling</b> .....   | <b>7</b>    |
| <b>7 Procedure</b> .....  | <b>7</b>    |
| 7.1 General for measuring on the horizontal drop .....                        | 7           |
| 7.1.1 Setting up the contact angle measuring system .....                     | 7           |
| 7.1.2 Test conditions .....   | 8           |
| 7.1.3 Conditioning of the test panels .....                                   | 8           |
| 7.2 Measurement .....   | 8           |
| 7.2.1 General .....   | 8           |
| 7.2.2 Static method .....   | 8           |
| 7.2.3 Dynamic method (progressive contact angle) .....                        | 9           |
| 7.2.4 Determination of the contact angle .....                                | 10          |
| <b>8 Evaluation</b> .....   | <b>10</b>   |
| 8.1 General .....   | 10          |
| 8.2 Owens-Wendt-Rabel-Kaelble method (OWRK method) .....                      | 10          |
| 8.3 Wu method .....   | 11          |
| <b>9 Precision</b> .....  | <b>12</b>   |
| 9.1 General .....   | 12          |
| 9.2 Repeatability limit, $r$ .....  | 12          |
| 9.3 Reproducibility limit, $R$ .....  | 12          |
| 9.4 Calculation in accordance with the Owens-Wendt-Rabel-Kaelble method ..... | 12          |
| <b>10 Test report</b> .....   | <b>13</b>   |
| <b>Annex A (informative) Notes on measuring practice</b> .....                | <b>14</b>   |
| <b>Bibliography</b> .....   | <b>18</b>   |