

# ISO 19403-6:2024-10 (E)

## Paints and varnishes - Wettability - Part 6: Measurement of dynamic advancing and receding angle by changing the volume of a drop

---

<b>Contents</b>	<b>Page</b>
<b>Foreword</b> .....	<b>iv</b>
<b>Introduction</b> .....	<b>v</b>
<b>1 Scope</b> .....	<b>1</b>
<b>2 Normative references</b> .....	<b>1</b>
<b>3 Terms and definitions</b> .....	<b>1</b>
<b>4 Principle</b> .....	<b>2</b>
<b>5 Apparatus and materials</b> .....	<b>2</b>
<b>6 Sampling</b> .....	<b>3</b>
<b>7 Procedure</b> .....	<b>4</b>
7.1 General for measuring on the horizontal drop.....	4
7.1.1 Setting up the contact angle measuring system.....	4
7.1.2 Test conditions.....	4
7.1.3 Conditioning of the test panels.....	4
7.1.4 Conditioning of the test liquids.....	4
7.2 Measurement.....	4
7.2.1 General.....	4
7.2.2 Measuring method.....	5
7.2.3 Determination of the contact angle.....	5
<b>8 Evaluation</b> .....	<b>5</b>
<b>9 Test report</b> .....	<b>8</b>
<b>Annex A (informative) Notes on sampling and treatment of test specimens</b> .....	<b>10</b>
<b>Bibliography</b> .....	<b>11</b>