

ISO 8502-12:2003-02 (E)

Preparation of steel substrates before application of paints and related products -
Tests for the assessment of surface cleanliness - Part 12: Field method for the
titrimetric determination of water-soluble ferrrous ions

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	1
3	Principle	1
4	Reagents	2
5	Apparatus	2
6	Removal of water-soluble contaminants from the surface	2
7	Procedure	2
8	Expression of results	3
9	Precision	3
10	Test report	3