

# ISO 21227-3:2007-04 (E)

## Paints and varnishes - Evaluation of defects on coated surfaces using optical imaging - Part 3: Evaluation of delamination and corrosion around a scribe

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		v
1 <b>Scope</b> .....		1
2 <b>Normative references</b> .....		1
3 <b>Terms and definitions</b> .....		1
4 <b>Principle</b> .....		1
5 <b>Requirements</b> .....		2
6 <b>Calibration</b> .....		2
7 <b>Procedure</b> .....		2
8 <b>Evaluation</b> .....		3
9 <b>Precision</b> .....		4
10 <b>Test report</b> .....		5
<b>Annex A (normative) Ratings in accordance with ISO 4628-8 to be used to evaluate the delamination and corrosion around a scribe</b> .....		<b>6</b>
<b>Annex B (informative) Extended evaluation</b> .....		<b>8</b>
<b>Bibliography</b> .....		<b>9</b>