

ISO 13319:2007-07 (E)

Determination of particle size distributions - Electrical sensing zone method

Contents		Page
Foreword		iv
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Symbols	2
5	Principle	3
6	General operation	4
6.1	Response	4
6.2	Size limits	4
6.3	Effect of coincident particle passage	4
6.4	Dead time	5
7	Repeatability of counts	6
8	Operational procedures	6
8.1	Instrument location	6
8.2	Linearity of the aperture/amplifier system	6
8.3	Linearity of the counting system	7
8.4	Choice of electrolyte solution	7
8.5	Preparation of electrolyte solution	7
8.6	Recommended sampling, sample splitting, sample preparation and dispersion	8
8.7	Choice of aperture(s) and analysis volume(s)	9
8.8	Clearing an aperture blockage	10
8.9	Stability of dispersion	10
8.10	Calibration	11
9	Analysis	11
10	Calculation of results	12
11	Instrument qualification	12
11.1	General	12
11.2	Report	12
Annex A (informative) Calibration for the measurement of porous and conductive particles		13
Annex B (informative) Technique using two (or more) apertures		16
Annex C (informative) Chi-squared test of the correctness of instrument operation or sample preparation		18
Annex D (informative) Table of materials and electrolyte solutions		20
Annex E (informative) Mass integration method		30
Annex F (informative) Calibration and control of frequently used apertures		36
Bibliography		37