

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	1
3	Terms, definitions, symbols and abbreviated terms	2
3.1	Terms and definitions	2
3.2	Symbols and abbreviated terms	6
4	Equipment	6
4.1	Cone penetrometer load sensors	6
4.2	Tolerances	6
4.3	Surface roughness	7
4.4	Cone penetrometer	7
4.5	Cone	8
4.6	Friction sleeve	9
4.7	Push rods	11
4.8	Inner rods	11
4.9	Measuring system	11
4.10	Thrust machine	12
5	Test procedures	12
5.1	Selection of type of cone penetrometer test	12
5.2	Selection of equipment and procedures	13
5.3	Position and level of thrust machine	15
5.4	Preparation	15
5.5	Pushing of the cone penetrometer	15
5.6	Use of friction reducer	15
5.7	Frequency of logging parameters	15
5.8	Measurement of cone penetration force for discontinuous penetration testing	15
5.9	Measurement of cone penetration force for continuous testing	16
5.10	Measurement of sleeve friction force for discontinuous testing with M2 cone penetrometers	16
5.11	Measurement of total penetration force for discontinuous testing	16
5.12	Measurement of total penetration force for continuous testing (TM4)	16
5.13	Measurement of the penetration length	16
5.14	Test completion	16
5.15	Equipment checks and calibrations	17
6	Test results	17
6.1	Measured parameters	17
6.2	Calculated parameters	17
7	Reporting	17
7.1	General	17
7.2	Reporting of test results	17
7.3	Presentation of test results	20
Annex A (normative) Maintenance, checks and calibration		21
Bibliography		23