

# DIN 66165-1:2016-08 (E)

## Particle size analysis - Sieving analysis - Part 1: Fundamentals

---

<b>Contents</b>		<b>Page</b>
Foreword .....		3
1	Scope .....	4
2	Normative references .....	4
3	Terms and definitions .....	4
4	Methods of test sieving .....	4
5	Factors affecting test sieving .....	5
5.1	General .....	5
5.2	Equipment- and process-related factors .....	5
5.2.1	Size and shape of sieve apertures, distribution of sieve aperture sizes .....	5
5.2.2	Effective sieving area .....	6
5.2.3	Movement of sieve or fluid .....	6
5.2.4	Sieving aids .....	6
5.2.5	Sieving using a set of test sieves .....	6
5.3	Material-related factors .....	6
5.3.1	Mass and bulk volume of the material to be sieved .....	6
5.3.2	Particle size distribution .....	7
5.3.3	Shape of particles .....	7
5.3.4	Tendency to agglomerate and to cohere .....	7
5.3.5	Susceptibility to abrasion and fracture .....	8
5.4	Sieving duration .....	8
6	Determination of cut point .....	9
7	Selecting the sieve aperture sizes .....	9
8	Analytical errors .....	10
9	Checking and maintenance of the test sieves .....	10
10	Calibration using reference material .....	11
10.1	Requirements to be met by the reference material .....	11
10.2	Calibration procedure .....	11
11	Determining the distribution of the sieve aperture sizes .....	11
Bibliography .....		12