

DIN EN 1279-6:2018-10 (E)

Glass in building - Insulating glass units - Part 6: Factory production control and periodic tests

Contents	Page
European foreword.....	5
1 Scope.....	7
2 Normative references.....	7
3 Terms and definitions and symbols.....	7
3.1 Terms and definitions.....	7
3.2 Symbols.....	8
4 Factory production control requirements.....	8
4.1 General.....	8
4.2 Organization.....	8
4.2.1 Responsibility and authority.....	8
4.2.2 Management representative for factory production control.....	8
4.2.3 Management review.....	8
4.3 Factory production control system.....	8
4.3.1 General.....	8
4.3.2 Personnel.....	9
4.3.3 Documentation.....	9
4.4 Equipment.....	9
4.4.1 Testing.....	9
4.4.2 Manufacturing.....	9
4.4.3 Inspection and testing.....	9
4.4.4 Non-complying materials / products.....	9
Annex A (normative) Inspection and testing tables of insulating glass units.....	10
A.1 General.....	10
A.2 Specific requirements.....	11
A.3 Use of proxy testing.....	11
Annex B (normative) Periodic testing and inspection.....	33
B.1 General.....	33
B.2 Frequency and sampling.....	33
B.2.1 Frequency.....	33
B.2.2 Sampling.....	33
B.3 Conformity to the system description.....	33
B.3.1 Inspection.....	33
B.3.2 Requirements.....	33
B.3.3 Corrective actions.....	34
B.4 Moisture penetration index and gas concentration.....	34
B.4.1 General.....	34
B.4.2 Procedure.....	34
B.4.3 Test procedure.....	34

B.4.4	Requirement.....	35
B.4.4.1	Requirement on T_i and moisture penetration index	35
B.4.4.2	Requirements on gas concentration.....	35
B.5	Corrective Actions in case of non-conformity	35
B.6	Report	35
Annex C (informative)	Adhesion test for leaded light strip.....	36
C.1	Purpose	36
C.2	Equipment.....	36
C.3	Test specimen	36
C.4	Procedure	36
C.5	Test report	37
Annex D (informative)	Sealant, adhesion measurements	38
D.1	General	38
D.2	Standard method	38
D.2.1	Instruments	38
D.2.2	Test specimens	38
D.2.2.1	Glass-glass specimen	38
D.2.2.2	Spacer-spacer specimen.....	39
D.2.3	Test procedure	39
D.2.4	Test report	39
D.3	Other methods	39
D.3.1	Tensile test.....	39
D.3.2	Butterfly test.....	40
Annex E (informative)	Sealants, hardness measurements.....	41
E.1	General	41
E.2	Instruments	41
E.3	Test specimen	41
E.4	Measurement	42
E.5	Report	42
Annex F (informative)	Two component sealants: check on the thoroughness of mixing.....	43
F.1	Purpose	43
F.2	Test specimen	43
F.3	Test procedure	43
F.4	Report	43
Annex G (informative)	Tightness check of hollow spacer closed by welding on the back.....	44
G.1	Purpose	44

G.2	Equipment	44
G.3	Test specimen.....	44
G.4	Procedure.....	44
G.5	Test report.....	44
Annex H (informative) Desiccant, water adsorption capacity check		45
H.1	General.....	45
H.2	Determination of the water adsorption capacity of desiccant in bulk	45
H.2.1	Principle	45
H.2.2	Equipment	45
H.2.3	Method	45
H.3	Determination of the water adsorption capacity of polymeric matrix incorporating desiccant.....	46
Annex I (informative) Desiccant Matrix Adhesion test in u-channels.....		47
I.1	General.....	47
I.2	Materials.....	47
I.3	Test procedure.....	47
I.4	Requirement.....	47
Annex J (informative) Adhesion tests for insulating glass units with prefabricated flexible spacer incorporating desiccant.....		48
J.1	Adhesion test of spacer to sealant.....	48
J.1.1	General.....	48
J.1.2	Materials.....	48
J.1.3	Test preparation and procedure	48
J.1.4	Requirements	48
J.2	Wet out strain and shear test.....	49
J.2.1	Materials.....	49
J.2.2	Test procedure	49
J.2.3	Requirements	53
Annex K (informative) Reference method for dew point temperature measurement.....		54
K.1	General.....	54
K.2	Apparatus and materials.....	54
K.3	Procedure.....	54
Bibliography.....		56