

# ISO 17123-2:2001-12 (E)

## Optics and optical instruments - Field procedures for testing geodetic and surveying instruments - Part 2: Levels

---

<b>Contents</b>		<b>Page</b>
<b>1</b>	<b>Scope .....</b>	<b>1</b>
<b>2</b>	<b>Normative references .....</b>	<b>1</b>
<b>3</b>	<b>Terms and definitions .....</b>	<b>2</b>
<b>4</b>	<b>General .....</b>	<b>2</b>
<b>5</b>	<b>Simplified test procedure .....</b>	<b>3</b>
<b>6</b>	<b>Full test procedure .....</b>	<b>5</b>
<b>Annexes A Example of the simplified test procedure .....</b>		<b>10</b>
<b>A.1</b>	<b>Measurements .....</b>	<b>10</b>
<b>A.2</b>	<b>Calculation .....</b>	<b>10</b>
<b>B</b>	<b>Example of the full test procedure .....</b>	<b>12</b>
<b>B.1</b>	<b>Measurements .....</b>	<b>12</b>
<b>B.2</b>	<b>Calculation .....</b>	<b>12</b>
<b>B.3</b>	<b>Statistical tests .....</b>	<b>13</b>