

# ISO 7726:1998-11 (E)

## Ergonomics of the thermal environment - Instruments for measuring physical quantities

---

Contents	Page
1 Scope .....	1
2 Normative reference.....	1
3 General .....	1
4 Measuring instruments.....	2
5 Specifications relating to measuring methods .....	5
Annex A Measurement of air temperature .....	12
Annex B Measurement of the mean radiant temperature .....	14
Annex C Measurement of plane radiant temperature .....	28
Annex D Measurement of the absolute humidity of the air.....	35
Annex E Measurement of air velocity.....	45
Annex F Measurement of surface temperature .....	48
Annex G Measurement of operative temperature .....	49
Annex H Bibliography .....	51