

# ISO 13779-3:2008-02 (E)

## Implants for surgery - Hydroxyapatite - Part 3: Chemical analysis and characterization of crystallinity and phase purity

---

<b>Contents</b>		<b>Page</b>
Foreword .....		v
Introduction .....		vi
<b>1</b>	<b>Scope .....</b>	<b>1</b>
<b>2</b>	<b>Normative references .....</b>	<b>1</b>
<b>3</b>	<b>Terms, definitions and symbols .....</b>	<b>1</b>
3.1	Terms and definitions .....	1
3.2	Symbols .....	2
<b>4</b>	<b>Analytical methods .....</b>	<b>2</b>
<b>5</b>	<b>Apparatus, reagents and calibration specimens .....</b>	<b>2</b>
5.1	Apparatus for chemical analysis .....	2
5.2	Reagents for chemical analysis .....	3
5.3	Apparatus and calibration specimens for X-ray diffraction analysis .....	3
5.4	Infrared apparatus .....	4
<b>6</b>	<b>X-Ray diffraction pattern collection .....</b>	<b>4</b>
6.1	General .....	4
6.2	Identification of the crystallized phases .....	4
<b>7</b>	<b>Preparation of the test sample .....</b>	<b>5</b>
7.1	Coatings .....	5
7.2	Bulk sample .....	5
7.3	X-ray analysis .....	5
<b>8</b>	<b>Plotting the calibration curves .....</b>	<b>6</b>
8.1	General .....	6
8.2	Plotting the calibration curves for the foreign phases .....	6
8.3	Plotting the calibration curves for the calculation of the calcium:phosphorus (Ca:P) ratio .....	7
<b>9</b>	<b>Chemical analysis .....</b>	<b>8</b>
9.1	General .....	8
9.2	Expression of results .....	8
<b>10</b>	<b>Ca:P ratio .....</b>	<b>8</b>
10.1	General .....	8
10.2	Procedure .....	9
10.3	Measurements on the sample .....	9
10.4	Choice of the diffraction peaks .....	9
10.5	Expression of results .....	9
<b>11</b>	<b>Qualitative and quantitative determination of the foreign phases .....</b>	<b>10</b>
11.1	Procedure .....	10
11.2	Expression of results .....	10
<b>12</b>	<b>Determination of the crystallinity ratio .....</b>	<b>10</b>
12.1	General .....	10
12.2	Preparation of the sample .....	10

12.3	Procedure .....	10
12.4	Expression of results .....	10
13	Degradation of ceramics .....	11
14	Test report .....	11
Annex A (informative) Contamination of calcium phosphate .....		12
Annex B (normative) Testing of the purity of the phases used in the production of the calibration curves .....		13
Annex C (informative) Examples of X-ray diffraction patterns collected from various mixtures used to plot the calibration curves .....		14
Annex D (normative) Positions of lines used to measure the crystallinity ratio .....		16
Annex E (informative) Examples of methods for the preparation of reference materials .....		17
Bibliography .....		19