

# DIN EN ISO 21987:2010-02 (E)

## Ophthalmic optics - Mounted spectacle lenses (ISO 21987:2009)

---

<b>Contents</b>		<b>Page</b>
Foreword .....		3
<b>1</b>	<b>Scope .....</b>	<b>4</b>
<b>2</b>	<b>Normative references .....</b>	<b>4</b>
<b>3</b>	<b>Terms and definitions .....</b>	<b>4</b>
<b>4</b>	<b>Classification .....</b>	<b>5</b>
<b>5</b>	<b>Requirements .....</b>	<b>5</b>
<b>5.1</b>	<b>Reference temperature .....</b>	<b>5</b>
<b>5.2</b>	<b>Lenses used in manufacturing complete spectacles .....</b>	<b>5</b>
<b>5.3</b>	<b>Optical requirements .....</b>	<b>5</b>
<b>5.4</b>	<b>Thickness tolerance .....</b>	<b>9</b>
<b>5.5</b>	<b>Positioning tolerances .....</b>	<b>9</b>
<b>6</b>	<b>Test methods .....</b>	<b>10</b>
<b>6.1</b>	<b>General .....</b>	<b>10</b>
<b>6.2</b>	<b>Measurement method for the back vertex power of single-vision lenses and the distance portion of multifocal and progressive-power lenses and near portion of degressive-power lenses .....</b>	<b>11</b>
<b>6.3</b>	<b>Measurement method for cylinder axis .....</b>	<b>11</b>
<b>6.4</b>	<b>Addition power measurement .....</b>	<b>11</b>
<b>6.5</b>	<b>6.6 Material and surface quality .....</b>	<b>13</b>
<b>6.7</b>	<b>Prism imbalance (relative prism error) measurement method for pairs of single-vision and multifocal lenses .....</b>	<b>13</b>
<b>7</b>	<b>Marking for progressive-power and degressive-power lenses .....</b>	<b>13</b>
<b>7.1</b>	<b>Permanent marking .....</b>	<b>13</b>
<b>7.2</b>	<b>8 Identification .....</b>	<b>14</b>
<b>9</b>	<b>Reference to ISO 21987 .....</b>	<b>14</b>
<b>Annex A (informative) Material and surface quality .....</b>		<b>15</b>
<b>Annex B (informative) Recommendations on mounting .....</b>		<b>16</b>
<b>Annex C (informative) Alternative methods for measuring prism imbalance (relative prism error) for pairs of single-vision and multifocal lenses .....</b>		<b>18</b>
<b>Bibliography .....</b>		<b>20</b>
<b>Requirements of EU Directive 93/42/EEC .....</b>		<b>21</b>
<b>Annex ZA (informative) Relationship between this European Standard and the Essential Non-permanent marking .....</b>		<b>14</b>
<b>Method for measuring position and tilt .....</b>		<b>13</b>