

# DIN EN ISO 21254-2:2011-10 (E)

## Lasers and laser-related equipment - Test methods for laser-induced damage threshold - Part 2: Threshold determination (ISO 21254-2:2011)

---

<b>Contents</b>		<b>Page</b>
Foreword .....		3
Introduction .....		4
<b>1</b>	<b>Scope .....</b>	<b>5</b>
<b>2</b>	<b>Normative references .....</b>	<b>5</b>
<b>3</b>	<b>Terms and definitions .....</b>	<b>5</b>
<b>4</b>	<b>Test methods .....</b>	<b>5</b>
<b>4.1</b>	<b>General .....</b>	<b>5</b>
<b>4.2</b>	<b>1-on-1 test method .....</b>	<b>5</b>
<b>4.3</b>	<b>S-on-1 test method .....</b>	<b>7</b>
<b>5</b>	<b>Accuracy .....</b>	<b>11</b>
<b>6</b>	<b>Test report .....</b>	<b>11</b>
<b>6.1</b>	<b>General .....</b>	<b>11</b>
<b>6.2</b>	<b>1-on-1 test .....</b>	<b>12</b>
<b>6.3</b>	<b>S-on-1 test .....</b>	<b>12</b>
	<b>Annex A (informative) Example of a measurement procedure (1-on-1 test) .....</b>	<b>13</b>
	<b>Annex B (informative) Example of a test report for a 1-on-1 test .....</b>	<b>19</b>
	<b>Annex C (informative) Example of a measurement procedure (S-on-1 test) .....</b>	<b>24</b>
	<b>Annex D (informative) Example of a test report for an S-on-1 test .....</b>	<b>28</b>
	<b>Annex E (informative) Extrapolation method for S-on-1 tests .....</b>	<b>35</b>
	<b>Annex F (informative) Conversion of damage data into defect densities .....</b>	<b>37</b>
	<b>Bibliography .....</b>	