

# ISO 9335:2012-10 (E)

## Optics and photonics - Optical transfer function - Principles and procedures of measurement

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		v
<b>1</b>	<b>Scope .....</b>	<b>1</b>
<b>2</b>	<b>Normative references .....</b>	<b>1</b>
<b>3</b>	<b>Terms and definitions .....</b>	<b>1</b>
<b>4</b>	<b>Measuring equipment and environment .....</b>	<b>1</b>
<b>4.1</b>	<b>General aspects .....</b>	<b>1</b>
<b>4.2</b>	<b>Environment .....</b>	<b>2</b>
<b>4.3</b>	<b>Measuring equipment .....</b>	<b>2</b>
<b>4.4</b>	<b>System components .....</b>	<b>3</b>
<b>5</b>	<b>Measurement procedures .....</b>	<b>10</b>
<b>5.1</b>	<b>General .....</b>	<b>10</b>
<b>5.2</b>	<b>Setting the measuring conditions .....</b>	<b>10</b>
<b>5.3</b>	<b>Additional considerations of measurement .....</b>	<b>11</b>
<b>5.4</b>	<b>Particular measuring conditions .....</b>	<b>13</b>
<b>6</b>	<b>Corrections to measured data .....</b>	<b>14</b>
<b>6.1</b>	<b>Normalization .....</b>	<b>14</b>
<b>6.2</b>	<b>Correction of the frequency scale .....</b>	<b>14</b>
<b>6.3</b>	<b>Correction of the measured modulation .....</b>	<b>14</b>
<b>6.4</b>	<b>Auxiliary imaging systems .....</b>	<b>15</b>
<b>7</b>	<b>Presentation of OTF data .....</b>	<b>15</b>
<b>7.1</b>	<b>General .....</b>	<b>15</b>
<b>7.2</b>	<b>Statement of identification and measuring conditions .....</b>	<b>15</b>
<b>7.3</b>	<b>Graphical presentation of OTF data .....</b>	<b>16</b>
<b>7.4</b>	<b>Numerical presentation .....</b>	<b>17</b>
<b>8</b>	<b>Accuracy checks .....</b>	<b>17</b>
<b>Annex A (informative)</b>	<b>Examples of the presentation of OTF data .....</b>	<b>19</b>
<b>Bibliography .....</b>		<b>24</b>