

DIN ISO 9022-2:2015-06 (E)

Optics and photonics - Environmental test methods - Part 2: Cold, heat and humidity (ISO 9022-2:2015)

Contents		Page
National foreword		3
National Annex NA (informative) Bibliography		4
Introduction		5
1	Scope	6
2	Normative references	6
3	General information and test conditions	6
4	Conditioning	6
4.1	General	6
4.2	Constant stress conditions	7
4.2.1	General	7
4.2.2	Conditioning method 10: Cold	7
4.2.3	Conditioning method 11: Dry heat	7
4.2.4	Conditioning method 12: Damp heat	7
4.2.5	Conditioning method 13: Condensation	7
4.3	Cycling exposure conditions	8
4.3.1	General	8
4.3.2	Conditioning method 14: Slow temperature change	8
4.3.3	Conditioning method 15: Rapid temperature change (temperature shock)	9
4.3.4	Conditioning method 16: Damp heat, cyclic	10
5	Procedure	12
5.1	General	12
5.2	Pre-test	12
6	Environmental test code	12
7	Specification	13