

ISO 9022-14:2015-04 (E)

Optics and photonics - Environmental test methods - Part 14: Dew, hoarfrost, ice

Contents		Page
Foreword		iv
Introduction		vi
1	Scope	1
2	Normative references	1
3	General information and test conditions	1
4	Conditioning	1
5	Procedure	2
5.1	General	2
5.2	Preconditioning	2
5.3	Test sequence	2
5.3.1	Conditioning method 75, degree of severity 01; conditioning method 76, degrees of severity 01 and 02	2
5.3.2	Conditioning method 76, degree of severity 03	3
5.3.3	Conditioning method 77	3
5.4	Recovery	3
5.5	Final test	3
6	Environmental test code	3
7	Specification	4
Annex A (informative)	Explanatory notes	5