

# DIN ISO 9022-3:2015-08 (E)

## Optics and photonics - Environmental test methods - Part 3: Mechanical stress (ISO 9022-3:2015)

---

<b>Contents</b>		<b>Page</b>
National foreword.....		3
National Annex NA (informative) <b>Bibliography</b> .....		4
<b>Introduction</b> .....		5
<b>1</b>	<b>Scope</b> .....	6
<b>2</b>	<b>Normative references</b> .....	6
<b>3</b>	<b>General information and test conditions</b> .....	6
<b>4</b>	<b>Conditioning</b> .....	7
4.1	Conditioning method 30: Shock.....	7
4.2	Conditioning method 31: Bump.....	7
4.3	Conditioning method 32: Drop and topple.....	8
4.4	Conditioning method 33: Free fall.....	8
4.5	Conditioning method 34: Bounce.....	8
4.6	Conditioning method 35: Steady-state acceleration, centrifugal.....	9
4.7	Conditioning method 36: Sinusoidal vibration.....	9
4.7.1	General.....	9
4.7.2	Vibration testing using sweep frequencies.....	9
4.7.3	Vibration fatigue test using characteristic frequencies.....	10
4.8	Conditioning method 37: Random vibration (wide-band) digitally controlled.....	10
<b>5</b>	<b>Procedure</b> .....	<b>11</b>
<b>6</b>	<b>Environmental test code</b> .....	<b>11</b>
<b>7</b>	<b>Specification</b> .....	<b>11</b>