

# ISO 13142:2015-07 (E)

## Electro-optical systems - Cavity ring-down technique for high-reflectance measurement

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		v
1	Scope .....	1
2	Normative references .....	1
3	Terms and definitions .....	1
4	Symbols used and units of measure .....	1
5	Test principles .....	2
5.1	General .....	2
5.2	Decay time of initial cavity and reflectance of cavity mirrors .....	2
5.3	Decay time of test cavity and reflectance of test sample .....	4
5.4	High reflectance measurement with an optical feedback CRD technique .....	4
6	Preparation of test sample and measurement arrangement .....	6
6.1	Test sample .....	6
6.2	Laser source .....	6
6.3	Ring-down cavity .....	6
6.4	Detection unit .....	6
6.5	Data acquisition and processing .....	7
6.6	Environment .....	7
7	Test procedure .....	7
7.1	General .....	7
7.2	Measurement of decay time of initial cavity .....	7
7.3	Calculation of reflectance of cavity mirrors .....	8
7.4	Measurement of decay time of test cavity .....	8
7.5	Calculation of reflectance of test sample .....	8
7.6	Assessments of the measurement .....	8
8	Main error factors .....	8
8.1	Influence of the instrumental response time on reflectance measurement .....	8
8.1.1	General .....	8
8.1.2	Multi-parameter fitting method .....	9
8.1.3	Data truncation method .....	9
8.2	Measurement error of the reflectance of cavity mirrors .....	10
8.3	Measurement error of the reflectance of test sample .....	10
9	Test report .....	10
Annex A (informative) Reflectance reliability check experiment .....		12
Annex B (informative) Test report .....		13
Bibliography .....		14