

DIN ISO 9335:2015-12 (E)

Optics and photonics - Optical transfer function - Principles and procedures of measurement (ISO 9335:2012)

| Contents | | Page |
|---|--|-------------|
| National foreword | | 3 |
| Introduction | | 5 |
| 1 | Scope | 6 |
| 2 | Normative references | 6 |
| 3 | Terms and definitions | 6 |
| 4 | Measuring equipment and environment | 6 |
| 4.1 | General aspects | 6 |
| 4.2 | Environment | 7 |
| 4.3 | Measuring equipment | 7 |
| 4.4 | System components | 8 |
| 5 | Measurement procedures | 15 |
| 5.1 | General | 15 |
| 5.2 | Setting the measuring conditions | 15 |
| 5.3 | Additional considerations of measurement | 16 |
| 5.4 | Particular measuring conditions | 18 |
| 6 | Corrections to measured data | 19 |
| 6.1 | Normalization | 19 |
| 6.2 | Correction of the frequency scale | 19 |
| 6.3 | Correction of the measured modulation | 19 |
| 6.4 | Auxiliary imaging systems | 20 |
| 7 | Presentation of OTF data | 20 |
| 7.1 | General | 20 |
| 7.2 | Statement of identification and measuring conditions | 20 |
| 7.3 | Graphical presentation of OTF data | 21 |
| 7.4 | Numerical presentation | 22 |
| 8 | Accuracy checks | 22 |
| Annex A (informative) Examples of the presentation of OTF data | | 24 |
| Bibliography | | 29 |
| DIN ISO 9335:2015-12 National Annex NA (informative) Bibliography | | 4 |