

DIN ISO 9335:2015-12 (E)

Optics and photonics - Optical transfer function - Principles and procedures of measurement (ISO 9335:2012)

Contents		Page
National foreword		3
Introduction		5
1	Scope	6
2	Normative references	6
3	Terms and definitions	6
4	Measuring equipment and environment	6
4.1	General aspects	6
4.2	Environment	7
4.3	Measuring equipment	7
4.4	System components	8
5	Measurement procedures	15
5.1	General	15
5.2	Setting the measuring conditions	15
5.3	Additional considerations of measurement	16
5.4	Particular measuring conditions	18
6	Corrections to measured data	19
6.1	Normalization	19
6.2	Correction of the frequency scale	19
6.3	Correction of the measured modulation	19
6.4	Auxiliary imaging systems	20
7	Presentation of OTF data	20
7.1	General	20
7.2	Statement of identification and measuring conditions	20
7.3	Graphical presentation of OTF data	21
7.4	Numerical presentation	22
8	Accuracy checks	22
Annex A (informative) Examples of the presentation of OTF data		24
Bibliography		29
DIN ISO 9335:2015-12 National Annex NA (informative) Bibliography		4