

DIN ISO 10110-7:2018-05 (E)

Optics and photonics - Preparation of drawings for optical elements and systems - Part 7: Surface imperfections (ISO 10110-7: 2017)

| Contents | Page |
|---|-------------|
| National foreword | 3 |
| National Annex NA (informative) Bibliography | 4 |
| Foreword | 5 |
| Introduction | 6 |
| 1 Scope | 7 |
| 2 Normative references | 7 |
| 3 Terms and definitions | 7 |
| 4 Indication in drawings | 9 |
| 4.1 General..... | 9 |
| 4.2 Dimensional specification method for optical elements and assemblies..... | 9 |
| 4.2.1 Maximum permissible surface imperfections..... | 9 |
| 4.2.2 Surface imperfection indication for the dimensional specification method..... | 12 |
| 4.2.3 Imperfections with a smaller grade number in the dimensional specification method..... | 12 |
| 4.2.4 Concentrations of surface imperfections in the dimensional specification method..... | 12 |
| 4.2.5 Test methods for the dimensional specification method..... | 13 |
| 4.3 Visibility specification method for optical elements and assemblies..... | 13 |
| 4.3.1 Maximum permissible surface imperfections..... | 13 |
| 4.3.2 Visibility specification imperfections with smaller grade number..... | 16 |
| 4.3.3 Concentrations of visibility imperfections..... | 16 |
| 4.3.4 Test method for visibility..... | 16 |
| 4.4 Location of the indication..... | 16 |
| Bibliography | 18 |