

ISO 13779-3:2018-12 (E)

Implants for surgery - Hydroxyapatite - Part 3: Chemical analysis and characterization of crystallinity ratio and phase purity

| Contents | | Page |
|--------------------|--|-------------|
| Foreword | | v |
| Introduction | | vi |
| 1 | Scope | 1 |
| 2 | Normative references | 1 |
| 3 | Terms and definitions | 1 |
| 4 | Chemical analysis | 4 |
| 4.1 | General | 4 |
| 4.2 | Analytical methods | 4 |
| 4.3 | Apparatus for chemical analysis | 5 |
| 4.4 | Reagents for chemical analysis | 5 |
| 4.5 | Procedure | 5 |
| 4.6 | Expression of results | 6 |
| 5 | X-ray diffraction analysis | 6 |
| 5.1 | General | 6 |
| 5.2 | Apparatus | 6 |
| 5.3 | Preparation of test samples | 7 |
| 5.3.1 | General | 7 |
| 5.3.2 | Coatings | 7 |
| 5.3.3 | Bulk sample | 7 |
| 5.4 | Calibration specimens | 7 |
| 5.5 | X-ray diffraction pattern collection | 7 |
| 5.5.1 | General | 7 |
| 5.5.2 | Identification of the crystallized phases | 8 |
| 5.6 | Calibration curves, limits and uncertainties | 8 |
| 5.6.1 | General | 8 |
| 5.6.2 | Plotting the calibration curves for the foreign phases | 8 |
| 5.6.3 | Detection limit (DL) and quantification limit (QL) of foreign phases | 9 |
| 5.6.4 | Uncertainty for determination of foreign phases content | 10 |
| 5.7 | Qualitative and quantitative determination of the foreign phases | 11 |
| 5.7.1 | Procedure | 11 |
| 5.7.2 | Expression of results | 11 |
| 5.8 | Calcium to phosphorous (Ca:P) ratio determination | 11 |
| 5.8.1 | General | 11 |
| 5.8.2 | Measurements on the sample | 11 |
| 5.8.3 | Uncertainty of Ca:P measurement | 12 |
| 5.8.4 | Expression of results | 12 |
| 5.9 | Determination of the crystallinity ratio | 13 |
| 5.9.1 | Rationale on different methods of determination of the crystallinity ratio | 13 |
| 5.9.2 | General | 13 |
| 5.9.3 | Procedure A | 13 |
| 5.9.4 | Procedure B | 14 |
| 5.9.5 | Uncertainty of the crystallinity ratio | 14 |
| 5.9.6 | Expression of results | 14 |
| 6 | Test report | 14 |

| | |
|---|-----------|
| Annex A (informative) Contamination of calcium phosphate | 16 |
| Annex B (normative) Testing of the purity of the phases used in the production of the calibration curves | 17 |
| Annex C (informative) Examples of X-ray diffraction patterns collected from various mixtures used to plot the calibration curves | 19 |
| Annex D (normative) Positions of hydroxyapatite lines used to measure the crystallinity ratio | 24 |
| Annex E (normative) Methods for the preparation of reference materials | 25 |
| Annex F (informative) Uncertainty calculation of Ca:P ratio | 28 |
| Annex G (informative) Quantitative Phase Analysis (QPA) by Rietveld Refinement of XRD Data | 30 |
| Annex H (informative) Alternative method: Determination of the crystallinity ratio | 31 |
| Bibliography | 32 |