

# ISO 12311:2023-12 (E)

## Personal protective equipment - Test methods for sunglasses and related eyewear

---

<b>Contents</b>		<b>Page</b>
Foreword.....		iv
<b>1</b>	<b>Scope</b> .....	<b>1</b>
<b>2</b>	<b>Normative references</b> .....	<b>1</b>
<b>3</b>	<b>Terms and definitions</b> .....	<b>1</b>
<b>4</b>	<b>Prerequisites</b> .....	<b>1</b>
<b>5</b>	<b>General test requirements</b> .....	<b>2</b>
<b>6</b>	<b>Test methods for mechanical properties</b> .....	<b>2</b>
6.1	Test method for frame deformation and filter retention.....	2
6.1.1	Principle.....	2
6.1.2	Apparatus.....	2
6.1.3	Procedure.....	3
6.1.4	Report.....	4
6.1.5	Uncertainty of measurement.....	4
6.2	Test method for increased endurance of sunglasses.....	5
6.2.1	Principle.....	5
6.2.2	Apparatus.....	5
6.2.3	Procedure.....	5
6.2.4	Report.....	10
6.2.5	Uncertainty of measurement.....	10
6.3	Test for resistance to perspiration of the sunglass frame.....	10
6.3.1	Principle.....	10
6.3.2	Apparatus and reagents.....	10
6.3.3	Procedure.....	11
6.3.4	Report.....	12
<b>Annex A (normative) Application of uncertainty of measurement</b> .....		<b>13</b>
<b>Bibliography</b> .....		<b>15</b>