

ISO 6760-1:2024-05 (E)

Optics and photonics - Test method for temperature coefficient of refractive index of optical glasses - Part 1: Minimum deviation method

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Principle	2
5	Measuring apparatus	3
5.1	Goniometer	3
5.2	Light source	3
5.3	Detector	3
5.4	Thermal chamber	3
6	Specimen prism	4
7	Measurement	4
7.1	Measurement of apex angle	4
7.2	Measurement of the angle of minimum deviation	4
8	Calculation	5
8.1	Absolute refractive index	5
8.2	Temperature coefficient of absolute refractive index	6
8.3	Temperature coefficient of relative refractive index	7
9	How to express the temperature coefficient of refractive index	8
10	Test report	8
Annex A (informative) Formula for calculating the refractive index of air		9
Annex B (informative) Calculation method for obtaining the relative refractive index of glass at an arbitrary temperature, air pressure and relative humidity		11
Annex C (informative) Half prism method		13
Annex D (informative) Interpolation formula for n/T		18
Annex E (informative) Derivation and verification of n_{rel}/T		19
Bibliography		22