

# ISO 6760-2:2024-05 (E)

## Optics and photonics - Test method for temperature coefficient of refractive index of optical glasses - Part 2: Interferometric method

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		v
1	Scope .....	1
2	Normative references .....	1
3	Terms and definitions .....	1
4	Principle .....	2
5	Measuring apparatus .....	2
5.1	General .....	2
5.2	Light sources .....	3
5.3	Thermal chamber .....	4
5.4	Flat plates .....	4
5.5	Interferometer for optical path length change measurement .....	5
5.6	Interferometer for expansion measurement .....	5
5.7	Detectors .....	5
5.8	Temperature sensor .....	6
5.9	Barometer .....	6
6	Measurement specimen .....	6
7	Measurement procedure .....	6
8	Calculation .....	7
8.1	Temperature coefficient of absolute refractive index .....	7
8.2	Linear expansion coefficient of specimen .....	8
8.3	Temperature coefficient of relative refractive index .....	8
9	How to express the temperature coefficient of refractive index .....	9
10	Test report .....	10
Annex A (informative)	Formula for calculating the refractive index of air .....	11
Annex B (normative)	Calculation of absolute refractive index of specimen at a given temperature using the temperature coefficient of refractive index .....	13
Annex C (informative)	Temperature coefficient of refractive index under continuous temperature change .....	17
Annex D (informative)	Sensor specifications .....	19
Annex E (informative)	How to find the deviation of interference fringes between two temperatures .....	21
Annex F (normative)	Flat plate requirements .....	23
Annex G (normative)	Heating rate and temperature distribution .....	25
Bibliography .....		26