

# ISO 6760-2:2024-05 (E)

## Optics and photonics - Test method for temperature coefficient of refractive index of optical glasses - Part 2: Interferometric method

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		v
1 Scope .....		1
2 Normative references .....		1
3 Terms and definitions .....		1
4 Principle .....		2
5 Measuring apparatus .....		2
5.1 General .....		2
5.2 Light sources .....		3
5.3 Thermal chamber .....		4
5.4 Flat plates .....		4
5.5 Interferometer for optical path length change measurement .....		5
5.6 Interferometer for expansion measurement .....		5
5.7 Detectors .....		5
5.8 Temperature sensor .....		6
5.9 Barometer .....		6
6 Measurement specimen .....		6
7 Measurement procedure .....		6
8 Calculation .....		7
8.1 Temperature coefficient of absolute refractive index .....		7
8.2 Linear expansion coefficient of specimen .....		8
8.3 Temperature coefficient of relative refractive index .....		8
9 How to express the temperature coefficient of refractive index .....		9
10 Test report .....		10
Annex A (informative) Formula for calculating the refractive index of air .....		11
Annex B (normative) Calculation of absolute refractive index of specimen at a given temperature using the temperature coefficient of refractive index .....		13
Annex C (informative) Temperature coefficient of refractive index under continuous temperature change .....		17
Annex D (informative) Sensor specifications .....		19
Annex E (informative) How to find the deviation of interference fringes between two temperatures .....		21
Annex F (normative) Flat plate requirements .....		23
Annex G (normative) Heating rate and temperature distribution .....		25
Bibliography .....		26