

# ISO/TS 6838:2024-07 (E)

## Ophthalmic optics - Contact lenses - Tolerances and methods for measurement of multifocal contact lens addition power

---

<b>Contents</b>		<b>Page</b>
<b>Foreword</b>		<b>iv</b>
<b>1</b>	<b>Scope</b>	<b>1</b>
<b>2</b>	<b>Normative references</b>	<b>1</b>
<b>3</b>	<b>Terms and definitions</b>	<b>1</b>
<b>4</b>	<b>Tolerances</b>	<b>2</b>
4.1	Tolerance limits	2
4.2	Conditioning of contact lenses prior to testing	2
4.3	Tolerances for rigid and soft contact lenses	3
<b>5</b>	<b>Methods of measurement for multifocal add power</b>	<b>3</b>
5.1	General	3
5.2	Wavefront sensor	3
5.2.1	Wavefront instrument specification	3
5.2.2	Wavefront calibration	3
5.2.3	Wavefront method of measurement	4
5.2.4	Power profile examples	4
5.2.5	Bifocal contact lens	6
5.3	Focimeter	7
5.3.1	Principle	7
5.3.2	Focimeter specification	8
5.3.3	Focimeter calibration	9
5.3.4	Measurement of most plus and least plus power	9
<b>6</b>	<b>Ring test results</b>	<b>10</b>
6.1	Ring test objectives	10
6.2	Ring test background	10
6.3	Ring test executive summary	11
6.3.1	WFS calibration verification using (13) certified low-power glass lenses	11
6.3.2	Focimeter calibration verification using (10) standard B+L calibration lenses	12
6.3.3	WFS gauge repeatability and reproducibility (GR&R) using PV2 MF HA lenses	12
6.3.4	Focimeter gauge repeatability and reproducibility (GR&R) using PV2 MF HA lenses	12
6.4	Calibration lens accuracy requirements	12
6.4.1	Focimeters	13
6.4.2	Wavefront sensor low-power lenses	13
<b>7</b>	<b>Discussion</b>	<b>15</b>
7.1	Ring test conclusions	15
7.2	Ring test recommendations	15
7.3	Multifocal add-power measurement challenges	15
7.3.1	Immersed wavefront sensor measurement challenges	15
7.3.2	In-air wavefront sensor measurement challenges	18
7.4	Questions to answer before the TS moves to become a standard	18
<b>Bibliography</b>		<b>20</b>