

# DIN EN ISO 11073-10404:2011-07 (E)

Health informatics - Personal health device communication - Part 10404: Device specialization - Pulse oximeter (ISO/IEEE 11073-10404:2010); English version EN ISO 11073-10404:2011

---

Inhalt	Seite
Foreword .....	6
Introduction.....	7
1. Overview.....	8
1.1 Scope .....	8
1.2 Purpose .....	8
1.3 Context .....	10
2. Normative references.....	10
3. Definitions, acronyms, and abbreviations .....	10
3.1 Definitions .....	10
3.2 Acronyms and abbreviations .....	11
4. Introduction to ISO/IEEE 11073 personal health devices.....	11
4.1 General .....	11
4.2 Introduction to IEEE 11073-20601 modeling constructs .....	12
4.2.1 General .....	12
4.2.2 Domain information model (DIM).....	12
4.2.3 Service model .....	12
4.2.4 Communication model.....	12
4.2.5 Implementing the models .....	12
5. Pulse oximeter device concepts and modalities .....	12
5.1 General .....	12
5.2 Device types.....	13
5.3 General concepts .....	13
5.3.1 Noninvasive measurement.....	13
5.3.2 Acquisition modes .....	13
5.4 Collected data .....	14
5.4.1 General .....	14
5.4.2 Percentage of arterial haemoglobin oxygen saturation .....	14
5.4.3 Pulse rate .....	15
5.4.4 Pulsatile occurrence .....	15
5.4.5 Plethysmogram.....	15
5.4.6 Pulsatile quality and signal characterization .....	15
5.5 Derived data .....	15
5.5.1 Limit indications .....	15
5.5.2 Pulsatile status .....	15
5.5.3 Device and sensor status .....	16
5.6 Stored data.....	16
5.7 Device configurations.....	16
6. Pulse oximeter DIM .....	16
6.1 Overview .....	16
6.2 Class extensions .....	16
6.3 Object instance diagram.....	16
6.4 Types of configuration.....	18
6.4.1 General .....	18
6.4.2 Standard configuration.....	18
6.4.3 Extended configuration .....	18
6.5 MDS object.....	19

6.5.1 MDS object attributes .....	19
6.5.2 MDS object methods .....	20
6.5.3 MDS object events .....	20
6.5.4 Other MDS services .....	22
6.6 Numeric objects .....	22
6.6.1 General.....	22
6.6.2 SpO <sub>2</sub> .....	22
6.6.3 Pulse rate.....	28
6.6.4 Pulsatile quality.....	33
6.7 Real-time sample array (RT-SA) objects .....	35
6.7.1 Plethysmographic waveform.....	35
6.8 Enumeration objects .....	37
6.8.1 General.....	37
6.8.2 Pulsatile occurrence.....	37
6.8.3 Pulsatile characteristic.....	39
6.8.4 Device and sensor annunciation conditions .....	41
6.9 PM-store objects .....	44
6.9.1 General.....	44
6.9.2 Persistent store model.....	44
6.9.3 PM-store object attributes .....	46
6.9.4 PM-store object methods.....	47
6.9.5 PM-store object events .....	47
6.9.6 PM-store object services .....	47
6.9.7 PM-segment objects .....	47
6.10 Scanner objects .....	49
6.10.1 General.....	49
6.10.2 Periodic configurable scanner attributes.....	51
6.10.3 Episodic configurable scanner attributes.....	53
6.11 Class extension objects.....	54
6.12 Pulse oximeter information model extensibility rules .....	54
7. Pulse oximeter service model .....	54
7.1 General.....	55
7.2 Object access services .....	55
7.3 Object access EVENT REPORT services .....	59
8. Pulse oximeter communication model .....	59
8.1 Overview .....	59
8.2 Communications characteristics .....	60
8.3 Association procedure .....	60
8.3.1 General.....	60
8.3.2 Agent procedure—association request .....	60
8.3.3 Manager procedure—association response.....	61
8.4 Configuring procedure .....	61
8.4.1 General.....	61
8.4.2 Pulse oximeter—standard configuration .....	62
8.5 Operating procedure .....	63
8.5.1 General.....	63
8.5.2 GET pulse oximeter MDS attributes.....	63
8.5.3 Measurement data transmission.....	63
8.6 Time synchronization .....	64
9. Test associations.....	64
9.1 Behavior with standard configuration.....	64
9.2 Behavior with extended configurations .....	64
10. Conformance.....	64
10.1 Applicability.....	64
10.2 Conformance specification.....	65
10.3 Levels of conformance.....	65
10.3.1 General.....	65
10.3.2 Conformance Level 1: base conformance .....	65
10.3.3 Conformance Level 2: extended nomenclature (ASN.1 and/or ISO/IEEE 11073-10101:2004 [B2]) .....	65

10.4	Implementation conformance statements (ICSs)	66
10.4.1	General format	66
10.4.2	General ICS	66
10.4.3	DIM MOC ICS	68
10.4.4	MOC attribute ICS	68
10.4.5	MOC notification ICS	69
10.4.6	MOC nomenclature ICS	69
1	(informative) Bibliography	71
2	(normative) Additional ASN.1 definitions	72
2.1	Numeric extensions for thresholds	72
2.2	Pulsatile characteristic bit mapping	72
2.3	Device and sensor status bit mapping	73
3	(normative) Allocation of identifiers	74
3.1	General	74
3.2	Definitions of terms and codes	74
3.3	Systematic derivations of terms and codes	75
4	(informative) Message sequence examples	76
a)	When the user connects the pulse oximeter, the manager does not yet know the agent's configuration and sends a response to the agent's Association Request with the result accepted-unknown-config. See E.2.2.2 and E.2.2.3 for the corresponding PDU examples.	76
b)	As a consequence of the previous action, the agent negotiates its configuration information to the manager. After getting confirmation that the manager accepts the agent's configuration, the agent device is ready to send measurements. Both devices enter the Operating state. See E.3.2.2 and E.3.2.3 for the corresponding PDU examples.	76
c)	Subsequently, the manager may request the MDS object attributes of the agent by sending a data message with the "Remote Operation Invoke   Get" command. As a response, the agent reports its MDS object attributes to the manager using a data message with the "Remote Operation Response   Get" command. See E.4.1.2 and E.4.1.3 for the corresponding PDU examples.	76
d)	As a next step, the user of the agent device takes a single measurement. The measurement data are transmitted to the manager using a confirmed event report. After having successfully received the measurement data, the manager sends a confirmation to the agent. See E.5.1 and E.5.2 for the corresponding PDU examples.	76
e)	The user ends the measurement session (e.g., by pushing the appropriate button on the device or by simply not using the device for a duration longer than a certain time period). As a consequence, the agent disassociates from the manager by sending an Association Release Request. The manager responds with an Association Release Response. See E.7.1 and E.7.2 for the corresponding PDU examples.	76
f)	When the agent requests to associate to the manager for the next measurement session (e.g., the next day), the manager responds that it has accepted the configuration, as it already knows the agent's configuration from the previous measurement session. Both devices transition directly to the Operating state.	76
g)	Finally, the last two steps shown are similar to steps d) and e). The user takes a single confirmed measurement followed by releasing the association.	76
5	(informative) PDU examples	78
5.1	General	78
5.2	Association information exchange	78
5.2.1	General	78
5.2.2	Extended configuration	78
5.2.3	Previously known extended configuration	79
5.2.4	Standard configuration	80
5.3	Configuration information exchange	81
5.3.1	General	81
5.3.2	Extended configuration	81
5.3.3	Known configuration	83
5.3.4	Standard configuration	83

5.4	GET MDS attributes service.....	84
5.5	Data reporting .....	85
5.5.1	Confirmed measurement data transmission .....	85
5.5.2	Response to confirmed measurement data transmission .....	86
5.6	Scanner example .....	86
5.6.1	General.....	86
5.6.2	Portion of configuration report describing a periodic configurable scanner .....	86
5.6.3	Measurement data transfer of a periodic configurable scanner.....	87
5.7	Disassociation.....	88
5.7.1	Association release request .....	88
5.7.2	Association release response .....	88