

# ISO 11140-5:2007-03 (E)

## Sterilization of health care products - Chemical indicators - Part 5: Class 2 indicators for Bowie and Dick-type air removal tests

---

Contents	Page
<b>Foreword</b> .....	iv
<b>Introduction</b> .....	v
<b>1 Scope</b> .....	1
<b>2 Normative references</b> .....	1
<b>3 Terms and definitions</b> .....	1
<b>4 General requirements</b> .....	2
<b>5 Indicator system</b> .....	2
<b>5.1 Format</b> .....	2
<b>5.2 Performance</b> .....	2
<b>6 Indicator</b> .....	3
<b>6.1 Format</b> .....	3
<b>6.2 Performance</b> .....	3
<b>7 Packaging and labelling</b> .....	4
<b>8 Quality assurance</b> .....	4
<b>9 Sampling conditioning</b> .....	4
<b>Annex A (normative) Determination of the degree of contrast between the colour of the substrate and the indicator agent</b> .....	5
<b>Annex B (normative) Method of determining uniform colour change on exposure to saturated steam</b> .....	6
<b>Annex C (normative) Method for determining indicator colour change on exposure to dry heat</b> .....	7
<b>Annex D (normative) Method for determining transfer of indicator agent to standard test pack</b> .....	8
<b>Annex E (normative) Standard test pack</b> .....	9
<b>Annex F (normative) Method of determining non-uniform colour change on exposure to a standard fault condition</b> .....	10
<b>Annex G (normative) Steam exposure apparatus</b> .....	11
<b>Bibliography</b> .....	12