

ISO 28927-2:2009-12 (E)

Hand-held portable power tools - Test methods for evaluation of vibration emission - Part 2: Wrenches, nut runners and screwdrivers

Contents		Page
Foreword		iv
Introduction		vi
1	Scope	1
2	Normative references	1
3	Terms, definitions and symbols	2
3.1	Terms and definitions	2
3.2	Symbols	3
4	Basic standards and vibration test codes	3
5	Description of the family of machines	3
6	Characterization of vibration	7
6.1	Direction of measurement	7
6.2	Location of measurements	7
6.3	Magnitude of vibration	13
6.4	Combination of vibration directions	13
7	Instrumentation requirements	13
7.1	General	13
7.2	Mounting of transducers	13
7.3	Frequency weighting filter	13
7.4	Integration time	13
7.5	Auxiliary equipment	14
7.6	Calibration	14
8	Testing and operating conditions of the machinery	14
8.1	General	14
8.2	Operating conditions	15
8.3	Other quantities to be specified	15
8.4	Attached equipment, work piece and task	15
8.5	Operators	18
9	Measurement procedure and validity	19
9.1	Reported vibration values	19
9.2	Declaration and verification of the vibration emission value	19
10	Measurement report	20
Annex A (informative)	Model test report for vibration emission of wrenches, nutrunners and screwdrivers	21
Annex B (normative)	Determination of uncertainty	23
Annex C (normative)	Brake devices -- Assembly drawings and specification of parts	26
Bibliography		39