

# DIN EN 13042-5:2009-12 (E)

## Machines and plants for the manufacture, treatment and processing of hollow glass - Safety requirements - Part 5: Pres ses (includes Amendment A1:2009)

---

<b>Contents</b>		<b>Page</b>
Foreword .....		3
<b>0</b>	<b>Introduction .....</b>	<b>4</b>
<b>1</b>	<b>Scope .....</b>	<b>4</b>
<b>2</b>	<b>Normative references .....</b>	<b>5</b>
<b>3</b>	<b>Terms and definitions - Symbols and abbreviated terms .....</b>	<b>6</b>
<b>4</b>	<b>List of significant hazards .....</b>	<b>7</b>
<b>5</b>	<b>Safety requirements and/or protective measures .....</b>	<b>9</b>
<b>6</b>	<b>Verification of safety requirements and/or protective measures .....</b>	<b>14</b>
<b>7</b>	<b>Information for use .....</b>	<b>14</b>
	<b>Annex A (informative) Examples of safeguarding hazards of crushing, drawing-in and entanglement at rotating tables .....</b>	<b>16</b>
	<b>Annex B (informative) Illustration of a mould set .....</b>	<b>20</b>
	<b>Annex ZA (informative) "Relationship between this European Standard and the Essential Requirements of EU Directive 98/37/EC" .....</b>	<b>21</b>
	<b>Annex ZB (informative) "Relationship between this European Standard and the Essential Requirements of EU Directive 2006/42/EC" .....</b>	<b>22</b>
	<b>Bibliography .....</b>	<b>23</b>