

# DIN EN 1822-2:2011-01 (E)

## High efficiency air filters (EPA, HEPA and ULPA) - Part 2: Aerosol production, measuring equipment, particle counting statistics

---

<b>Contents</b>		<b>Page</b>
Foreword .....		3
Introduction .....		4
1	Scope .....	5
2	Normative references .....	5
3	Terms and definitions .....	5
4	Aerosol production .....	5
4.1	General .....	5
4.2	Aerosol substances .....	5
4.3	Producing monodisperse aerosols .....	7
4.3.1	Condensation methods .....	7
4.3.2	Particle size classification .....	11
4.4	Generating polydisperse aerosols .....	11
4.5	Neutralisation of aerosols .....	11
4.6	Minimum performance parameters for aerosol generators .....	12
4.7	Sources of error .....	12
4.8	Maintenance and inspection .....	12
5	Measuring devices .....	12
5.1	Optical particle counters .....	12
5.1.1	Operation .....	12
5.1.2	Minimum performance parameters .....	13
5.1.3	Sources of error and limit errors .....	14
5.1.4	Maintenance and inspection .....	14
5.1.5	Calibration .....	14
5.2	Condensation nucleus counter .....	14
5.2.1	Operation .....	14
5.2.2	Minimum performance parameters .....	16
5.2.3	Sources of error and limit errors .....	16
5.2.4	Maintenance and inspection .....	17
5.2.5	Calibration .....	17
5.3	Differential mobility analyser .....	17
5.3.1	Operation .....	17
5.3.2	Minimum performance parameters .....	18
5.3.3	Sources of error and limit errors .....	18
5.3.4	Maintenance and inspection .....	19
5.3.5	Calibration .....	19
5.4	Particle size analysis system on the basis of differential mobility analysis .....	19
5.4.1	Operation .....	19
5.4.2	Minimum performance parameters .....	19
5.4.3	Sources of errors and error limits .....	19
5.4.4	Maintenance and inspection .....	19
5.4.5	Calibration .....	19
5.5	Dilution systems .....	20
5.5.1	Operation .....	20
5.5.2	Minimum performance parameters .....	20
5.5.3	Sources of error and limit errors .....	20

5.5.4	Maintenance and inspection .....	20
5.6	Differential pressure measuring equipment .....	20
5.7	Absolute pressure measuring equipment .....	21
5.8	Thermometers .....	21
5.9	Hygrometer .....	21
6	Maintenance and inspection intervals .....	21
7	Particle counting statistics .....	23
	Bibliography .....	25