

DIN EN 1822-4:2011-01 (E)

High efficiency air filters (EPA, HEPA and ULPA) - Part 4: Determining leakage of filter elements (scan method)

Contents		Page
Foreword		4
Introduction		5
1	Scope	6
2	Normative references	6
3	Terms and definitions	6
4	Description of the procedure	7
5	Test filter	8
6	Test apparatus	8
6.1	Set-up of the test apparatus	8
6.2	Test duct	11
6.2.1	Test air conditioning	11
6.2.2	Adjustment of the volume flow rate	11
6.2.3	Measurement of the volume flow rate	11
6.2.4	Aerosol mixing duct	11
6.2.5	Test filter mounting assembly	11
6.2.6	Measuring points for the pressure difference	11
6.2.7	Sampling, upstream	11
6.2.8	Screening	12
6.3	Scanning assembly	12
6.3.1	General	12
6.3.2	Sampling, downstream	12
6.3.3	Probe arm	13
6.3.4	Aerosol transport lines	13
6.3.5	Provisions to move the probe	13
6.4	Aerosol generation and measurement techniques	13
6.4.1	General	13
6.4.2	Set-up for testing with a monodisperse test aerosol	14
6.4.3	Set-up for testing with a polydisperse test aerosol	14
7	Test air	14
8	Test procedure	15
8.1	General	15
8.2	Preparatory checks	15
8.3	Starting up the aerosol generator	16
8.4	Preparing the test filter	16
8.4.1	Installing the test filter	16
8.4.2	Flushing the test filter	16
8.5	Testing	16
8.5.1	Measuring the pressure drop	16
8.5.2	Testing with monodisperse test aerosol	17
8.5.3	Testing with polydisperse test aerosol	17
8.5.4	Leak testing (local penetration)	17
8.5.5	Determining the mean efficiency of the filter element	17

9	Evaluation	18
9.1	Calculating the penetration and the efficiency	18
9.2	Local penetration	19
9.3	Mean efficiency	20
9.4	Classification	20
10	Test report	20
11	Maintenance and inspection of the test apparatus	21
Annex A (normative) Oil Thread Leak Test		23
Annex B (normative) Determining the test parameters		24
B.1	General	24
B.2	Boundary conditions	24
B.3	Test filter data	24
B.4	Data for the apparatus	25
B.4.1	Particle counters	25
B.4.2	Downstream sampling probes	25
B.4.3	Loss factor	26
B.5	Sequence of calculation steps	26
B.6	Checking the isokinetic sampling	27
B.7	Choosing the probe speed	28
B.8	Minimum aerosol concentration	29
B.9	Maximum aerosol concentration	30
B.10	Leak signal	31
B.10.1	Effective value	31
B.10.2	Signal difference	32
Annex C (informative) Example of an application with evaluation		34
Annex D (informative) Leak Test with solid PSL Aerosol		37
D.1	Background	37
D.2	General Remarks	37
D.3	Test Procedure	37
D.4	Test Protocol	39
Annex E (informative) 0,3 µm - 0,5 µm Particle Efficiency Leak Test		40
Bibliography		42