

# DIN EN ISO 11148-10:2012-06 (E)

## Hand-held non-electric power tools - Safety requirements - Part 10: Compression power tools (ISO 11148-10:2011)

---

| <b>Contents</b>  |   | <b>Page</b> |
|--|---|-------------|
| Introduction .....   |   | 4           |
| <b>1</b>   | <b>Scope .....</b>  | <b>5</b>    |
| <b>2</b>   | <b>Normative references .....</b>                                     | <b>6</b>    |
| <b>3</b>   | <b>Terms and definitions .....</b>                                    | <b>6</b>    |
| <b>3.1</b>   | <b>General terms and definitions .....</b>                            | <b>6</b>    |
| <b>3.2</b>   | <b>Terms and definitions related to compression power tools .....</b> | <b>8</b>    |
| <b>4</b>   | <b>Safety requirements and/or protective measures .....</b>           | <b>9</b>    |
| <b>4.1</b>   | <b>General .....</b>  | <b>9</b>    |
| <b>4.2</b>   | <b>Mechanical safety .....</b>  | <b>9</b>    |
| <b>4.3</b>   | <b>Thermal safety .....</b>   | <b>9</b>    |
| <b>4.4</b>   | <b>Noise reduction .....</b>  | <b>9</b>    |
| <b>4.5</b>   | <b>Vibration .....</b>  | <b>10</b>   |
| <b>4.6</b>   | <b>Materials and substances processed, used or exhausted .....</b>    | <b>11</b>   |
| <b>4.7</b>   | <b>Ergonomics .....</b>   | <b>11</b>   |
| <b>4.8</b>   | <b>Controls .....</b>   | <b>11</b>   |
| <b>5</b>   | <b>Verification .....</b>   | <b>12</b>   |
| <b>5.1</b>   | <b>General conditions for tests .....</b>                             | <b>12</b>   |
| <b>5.2</b>   | <b>Noise .....</b>  | <b>12</b>   |
| <b>5.3</b>   | <b>Vibration .....</b>  | <b>12</b>   |
| <b>5.4</b>   | <b>Unintentional start .....</b>                                      | <b>12</b>   |
| <b>5.5</b>   | <b>Power tool construction .....</b>                                  | <b>12</b>   |
| <b>5.6</b>   | <b>Structure of verification .....</b>                                | <b>13</b>   |
| <b>6</b>   | <b>Information for use .....</b>                                      | <b>13</b>   |
| <b>6.1</b>   | <b>Marking, signs and written warnings .....</b>                      | <b>13</b>   |
| <b>6.2</b>   | <b>Instruction handbook .....</b>                                     | <b>14</b>   |
| <b>6.3</b>   | <b>Operating instructions .....</b>                                   | <b>18</b>   |
| <b>6.4</b>   | <b>Data .....</b>   | <b>18</b>   |
| <b>6.5</b>   | <b>Maintenance instructions .....</b>                                 | <b>19</b>   |
| <b>Annex A (informative) List of significant hazards .....</b>   |   | <b>20</b>   |
| <b>Annex B (informative) Examples of compression power tools covered by this part of ISO 11148 .....</b> |   | <b>21</b>   |
| <b>Annex C (normative) Symbols for labels and signs .....</b>  |   | <b>22</b>   |
| <b>Bibliography .....</b>  |   | <b>24</b>   |