

# DIN EN ISO 19085-17:2021-12 (E)

## Woodworking machines - Safety - Part 17: Edge banding machines fed by chains (ISO 19085-17:2021)

<b>Contents</b>		<b>Page</b>
<b>European foreword</b> .....		<b>5</b>
<b>Annex ZA (informative) Relationship between this International Standard and the essential requirements of EU Directive 2006/42/EC aimed to be covered</b> .....		<b>6</b>
<b>Foreword</b> .....		<b>9</b>
<b>Introduction</b> .....		<b>10</b>
<b>1</b>	<b>Scope</b> .....	<b>12</b>
<b>2</b>	<b>Normative references</b> .....	<b>13</b>
<b>3</b>	<b>Terms and definitions</b> .....	<b>14</b>
<b>4</b>	<b>Safety requirements and measures for controls</b> .....	<b>20</b>
4.1	Safety and reliability of control systems.....	20
4.2	Control devices.....	20
4.3	Start.....	20
4.3.1	Direct start.....	20
4.3.2	Start via control power-on.....	21
4.3.3	Integrated feed.....	21
4.4	Safe stops.....	21
4.4.1	General.....	21
4.4.2	Normal stop.....	21
4.4.3	Operational stop.....	22
4.4.4	Emergency stop.....	22
4.5	Braking function of tools.....	22
4.6	Mode selection.....	22
4.6.1	Units' Manual adjustments mode (MODE 2).....	23
4.6.2	Fine adjustment mode (MODE 3).....	23
4.6.3	Feed chains greasing mode (MODE 4).....	24
4.7	Tool speed changing.....	25
4.7.1	Speed changing by shifting the belts on the pulleys.....	25
4.7.2	Speed changing by incremental speed change motor.....	25
4.7.3	Infinitely variable speed by frequency inverter.....	25
4.8	Failure of any power supply.....	25
4.9	Manual reset control.....	25
4.10	Standstill detection and monitoring.....	25
4.11	Machine moving parts speed monitoring.....	25
4.12	Time delay.....	25
4.13	Teleservice.....	25
<b>5</b>	<b>Safety requirements and measures for protection against mechanical hazards</b> .....	<b>25</b>
5.1	Stability.....	25
5.2	Risk of break-up during operation.....	26
5.3	Tool and tool fixing design.....	26
5.3.1	General.....	26
5.3.2	Spindle locking.....	26
5.3.3	Circular saw blade fixing device.....	26
5.3.4	Flange dimension for circular saw blades.....	26
5.3.5	Spindle rings.....	26
5.4	Braking.....	27
5.4.1	Braking of tools.....	27
5.4.2	Maximum run-down time.....	27
5.4.3	Brake release.....	27
5.5	Safeguards.....	27
5.5.1	Fixed guards.....	27
5.5.2	Interlocking moveable guards.....	27

5.5.3	Hold-to-run control.....	28
5.5.4	Two-hand control.....	28
5.5.5	Electro-sensitive protective equipment (ESPE).....	28
5.5.6	Pressure-sensitive protective equipment (PSPE).....	28
5.5.7	Enabling control.....	28
5.6	Prevention of access to hazardous moving parts.....	28
5.6.1	Guarding of tools installed inside the integral enclosure.....	28
5.6.2	Guarding of external milling units.....	28
5.6.3	Guarding of sanding belts.....	29
5.6.4	Guarding of the edge banding zone.....	29
5.6.5	Access between machine halves on double-end machines.....	29
5.6.6	Access to hazard points through the slot between chain beam and top pressure beam.....	30
5.6.7	Guarding of drives.....	31
5.6.8	Safeguarding of the feed mechanisms.....	31
5.6.9	Safeguarding of machine half movement on double-end machines.....	34
5.7	Impact hazard.....	37
5.8	Clamping devices.....	37
5.9	Measures against ejection.....	37
5.9.1	General.....	37
5.9.2	Guards materials and characteristics.....	38
5.9.3	Devices to minimize ejection of rigid edges.....	38
5.9.4	Height adjustments of feed mechanism.....	39
5.10	Workpiece supports and guides.....	39
5.10.1	General.....	39
5.10.2	Additional workpiece support at the outfeed.....	39
5.10.3	Transversal infeed device.....	40
5.10.4	Automatic panel returner.....	40
<b>6</b>	<b>Safety requirements and measures for protection against other hazards.....</b>	<b>41</b>
6.1	Fire.....	41
6.2	Noise.....	42
6.2.1	Noise reduction at the design stage.....	42
6.2.2	Noise emission measurement and declaration.....	42
6.3	Emission of chips and dust.....	42
6.4	Electricity.....	42
6.5	Ergonomics and handling.....	42
6.6	Lighting.....	42
6.7	Pneumatics.....	42
6.8	Hydraulics.....	42
6.9	Electromagnetic compatibility.....	42
6.10	Laser.....	43
6.11	Static electricity.....	43
6.12	Errors of fitting.....	43
6.13	Isolation.....	43
6.14	Maintenance.....	43
6.15	Relevant but not significant hazards.....	43
6.16	Extreme temperatures.....	43
6.17	Substances.....	44
6.18	Artificial optical radiation.....	44
<b>7</b>	<b>Information for use.....</b>	<b>44</b>
7.1	Warning devices.....	44
7.2	Marking.....	44
7.2.1	General.....	44
7.2.2	Additional markings.....	44
7.3	Instruction handbook.....	45
7.3.1	General.....	45
7.3.2	Additional information.....	45

<b>Annex A</b> (informative) <b>List of significant hazards</b> .....	<b>47</b>
<b>Annex B</b> (informative) <b>Performance level required</b> .....	<b>49</b>
<b>Annex C</b> (normative) <b>Stability test</b> .....	<b>51</b>
<b>Annex D</b> (normative) <b>Test for braking function</b> .....	<b>52</b>
<b>Annex E</b> (normative) <b>Impact test for guards</b> .....	<b>53</b>
<b>Annex F</b> (normative) <b>Noise test code</b> .....	<b>54</b>
<b>Bibliography</b> .....	<b>59</b>