

DIN EN ISO 19085-6:2025-04 (E)

Woodworking machines - Safety - Part 6: Single spindle vertical moulding machines (toupie) (ISO 19085-6:2024)

Contents		Page
European foreword		5
Annex ZA (informative) Relationship between this European Standard and the essential requirements of Directive 2006/42/EC aimed to be covered		6
Foreword		9
Introduction		10
1	Scope	12
2	Normative references	13
3	Terms and definitions	13
4	Safety requirements and measures for controls	20
4.1	Safety and reliability of control systems.....	20
4.2	Control devices.....	20
4.3	Start.....	21
4.3.1	Direct start.....	21
4.3.2	Start via control power-on.....	21
4.4	Safe stops.....	22
4.4.1	General.....	22
4.4.2	Normal stop.....	22
4.4.3	Operational stop.....	22
4.4.4	Emergency stop.....	22
4.5	Braking function of tools.....	22
4.6	Mode selection.....	22
4.7	Tool speed changing.....	22
4.7.1	Speed changing by shifting the belts on the pulleys.....	22
4.7.2	Speed changing by incremental speed change motor.....	22
4.7.3	Infinitely variable speed by frequency inverter.....	22
4.7.4	Speed limiting device for tenoning.....	22
4.7.5	Changing the direction of tool rotation.....	23
4.8	Failure of any power supply.....	23
4.9	Manual reset control.....	24
4.10	Standstill detection and monitoring.....	24
4.11	Machine moving parts speed monitoring.....	24
4.12	Time delay.....	24
4.13	Teleservice.....	24
4.14	Power-driven adjustment of arbor, demountable power feed unit, fences and table insert.....	24
5	Safety requirements and measures for protection against mechanical hazards	25
5.1	Stability.....	25
5.2	Risk of break-up during operation.....	25
5.3	Tool and tool fixing design.....	25
5.3.1	General.....	25
5.3.2	Spindle locking.....	28
5.3.3	Circular saw blade fixing device.....	28
5.3.4	Flange dimension for circular saw blades.....	28
5.3.5	Arbor rings.....	28
5.3.6	Quick tool/arbor change system.....	28
5.3.7	Manual adjustment of arbor height.....	29
5.3.8	Manual adjustment of arbor inclination.....	29
5.4	Braking.....	30
5.4.1	Braking of tools.....	30

5.4.2	Maximum run-down time	30
5.4.3	Brake release	30
5.5	Safeguards	30
5.5.1	Fixed guards	30
5.5.2	Interlocking movable guards	30
5.5.3	Hold-to-run control	30
5.5.4	Two-hand control	30
5.5.5	Electro-sensitive protective equipment (ESPE)	30
5.5.6	Pressure-sensitive protective equipment (PSPE)	30
5.5.7	Enabling control	31
5.6	Prevention of access to hazardous moving parts	31
5.6.1	Access to the tool below the table	31
5.6.2	Safeguarding for straight work	31
5.6.3	Safeguarding for curved work	33
5.6.4	Safeguarding for tenoning	34
5.6.5	Safeguarding the glass bead saw blade	35
5.6.6	Guarding of drives	35
5.7	Impact hazard	35
5.8	Clamping devices	35
5.9	Measures against ejection	35
5.9.1	General	35
5.9.2	Guards materials and characteristics	35
5.9.3	Anti-kickback devices	36
5.10	Workpiece supports and guides	38
5.10.1	Machine table	38
5.10.2	Workpiece guiding for straight work	41
5.10.3	Workpiece guiding for curved work	42
5.11	Safety appliances	43
6	Safety requirements and measures for protection against other hazards	43
6.1	Fire	43
6.2	Noise	43
6.2.1	Noise reduction at the design stage	43
6.2.2	Noise emission measurement and declaration	44
6.3	Emission of chips and dust	44
6.4	Electricity	44
6.5	Ergonomics and handling	44
6.6	Lighting	44
6.7	Pneumatics	44
6.8	Hydraulics	45
6.9	Electromagnetic compatibility	45
6.10	Laser	45
6.11	Static electricity	45
6.12	Errors of fitting	45
6.13	Isolation	45
6.14	Maintenance	45
6.15	Relevant but not significant hazards	45
7	Information for use	45
7.1	Warning devices	45
7.2	Marking	45
7.2.1	General	45
7.2.2	Additional markings	45
7.3	Instruction handbook	46
7.3.1	General	46
7.3.2	Additional information	46
	Annex A (informative) List of significant hazards	49
	Annex B (informative) Performance level required	51
	Annex C (normative) Stability test	52
	Annex D (normative) Test for braking function	53
	Annex E (normative) Impact test for guards	54

Annex F (normative) Noise test code..... 55
Annex G (informative) Determination of maximum spindle speeds for single piece arbors..... 58
Annex H (normative) Rigidity test for pressure pads, hand protectors and guiding steadies..... 62
Bibliography..... 68