

ISO 13577-4:2022-07 (E)

Industrial furnaces and associated processing equipment - Safety - Part 4: Protective systems

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	1
3	Terms and definitions	2
4	Design requirements for equipment in a protective system	4
4.1	General	4
4.2	Requirements for protective systems	6
4.2.1	Overview of methods	6
4.2.2	Method A	7
4.2.3	Method BC	8
4.2.4	Method D	10
4.3	Fault assessment for the wired section of protective systems	11
4.4	Failure of utilities	12
4.5	Reset	12
5	Information for use	12
Annex A (informative) Explanation of techniques and measures for avoiding systematic faults		13
Annex B (normative) Wiring of protective systems		15
Annex C (informative) Examples for the determination of safety integrity level (SIL) or performance level (PL) using the risk graph method		29
Annex D (informative) Example of a risk assessment for one safety instrumented function using the method according to the IEC 61511:2016 series		45
Annex E (informative) Examples for protective functions		53
Annex F (normative) Requirements for application software		82
Bibliography		84