

# ISO 13577-4:2022-07 (E)

## Industrial furnaces and associated processing equipment - Safety - Part 4: Protective systems

---

Contents	Page
<b>Foreword</b> .....	iv
<b>Introduction</b> .....	v
<b>1 Scope</b> .....	1
<b>2 Normative references</b> .....	1
<b>3 Terms and definitions</b> .....	2
<b>4 Design requirements for equipment in a protective system</b> .....	4
<b>4.1 General</b> .....	4
<b>4.2 Requirements for protective systems</b> .....	6
<b>4.2.1 Overview of methods</b> .....	6
<b>4.2.2 Method A</b> .....	7
<b>4.2.3 Method BC</b> .....	8
<b>4.2.4 Method D</b> .....	10
<b>4.3 Fault assessment for the wired section of protective systems</b> .....	11
<b>4.4 Failure of utilities</b> .....	12
<b>4.5 Reset</b> .....	12
<b>5 Information for use</b> .....	12
<b>Annex A (informative) Explanation of techniques and measures for avoiding systematic faults</b> .....	13
<b>Annex B (normative) Wiring of protective systems</b> .....	15
<b>Annex C (informative) Examples for the determination of safety integrity level (SIL) or performance level (PL) using the risk graph method</b> .....	29
<b>Annex D (informative) Example of a risk assessment for one safety instrumented function using the method according to the IEC 61511:2016 series</b> .....	45
<b>Annex E (informative) Examples for protective functions</b> .....	53
<b>Annex F (normative) Requirements for application software</b> .....	82
<b>Bibliography</b> .....	84