

ISO 19085-6:2024-04 (E)

Woodworking machines - Safety - Part 6: Single spindle vertical moulding machines (toupie)

Contents		Page
Foreword		vi
Introduction		vii
1	Scope	1
2	Normative references	2
3	Terms and definitions	2
4	Safety requirements and measures for controls	9
4.1	Safety and reliability of control systems	9
4.2	Control devices	9
4.3	Start	10
4.3.1	Direct start	10
4.3.2	Start via control power-on	10
4.4	Safe stops	11
4.4.1	General	11
4.4.2	Normal stop	11
4.4.3	Operational stop	11
4.4.4	Emergency stop	11
4.5	Braking function of tools	11
4.6	Mode selection	11
4.7	Tool speed changing	11
4.7.1	Speed changing by shifting the belts on the pulleys	11
4.7.2	Speed changing by incremental speed change motor	11
4.7.3	Infinitely variable speed by frequency inverter	11
4.7.4	Speed limiting device for tenoning	11
4.7.5	Changing the direction of tool rotation	12
4.8	Failure of any power supply	12
4.9	Manual reset control	13
4.10	Standstill detection and monitoring	13
4.11	Machine moving parts speed monitoring	13
4.12	Time delay	13
4.13	Teleservice	13
4.14	Power-driven adjustment of arbor, demountable power feed unit, fences and table insert	13
5	Safety requirements and measures for protection against mechanical hazards	14
5.1	Stability	14
5.2	Risk of break-up during operation	14
5.3	Tool and tool fixing design	14
5.3.1	General	14
5.3.2	Spindle locking	17
5.3.3	Circular saw blade fixing device	17
5.3.4	Flange dimension for circular saw blades	17
5.3.5	Arbor rings	17
5.3.6	Quick tool/arbor change system	17
5.3.7	Manual adjustment of arbor height	18
5.3.8	Manual adjustment of arbor inclination	18
5.4	Braking	19
5.4.1	Braking of tools	19
5.4.2	Maximum run-down time	19
5.4.3	Brake release	19
5.5	Safeguards	19

5.5.1	Fixed guards.....	19
5.5.2	Interlocking movable guards	19
5.5.3	Hold-to-run control.....	19
5.5.4	Two-hand control.....	19
5.5.5	Electro-sensitive protective equipment (ESPE)	19
5.5.6	Pressure-sensitive protective equipment (PSPE).....	19
5.5.7	Enabling control.....	20
5.6	Prevention of access to hazardous moving parts.....	20
5.6.1	Access to the tool below the table.....	20
5.6.2	Safeguarding for straight work.....	20
5.6.3	Safeguarding for curved work.....	22
5.6.4	Safeguarding for tenoning.....	23
5.6.5	Safeguarding the glass bead saw blade.....	24
5.6.6	Guarding of drives.....	24
5.7	Impact hazard.....	24
5.8	Clamping devices.....	24
5.9	Measures against ejection.....	24
5.9.1	General.....	24
5.9.2	Guards materials and characteristics.....	24
5.9.3	Anti-kickback devices.....	25
5.10	Workpiece supports and guides.....	27
5.10.1	Machine table.....	27
5.10.2	Workpiece guiding for straight work.....	30
5.10.3	Workpiece guiding for curved work.....	31
5.11	Safety appliances.....	32
6	Safety requirements and measures for protection against other hazards.....	32
6.1	Fire.....	32
6.2	Noise.....	32
6.2.1	Noise reduction at the design stage.....	32
6.2.2	Noise emission measurement and declaration.....	33
6.3	Emission of chips and dust.....	33
6.4	Electricity.....	33
6.5	Ergonomics and handling.....	33
6.6	Lighting.....	33
6.7	Pneumatics.....	33
6.8	Hydraulics.....	34
6.9	Electromagnetic compatibility.....	34
6.10	Laser.....	34
6.11	Static electricity.....	34
6.12	Errors of fitting.....	34
6.13	Isolation.....	34
6.14	Maintenance.....	34
6.15	Relevant but not significant hazards.....	34
7	Information for use.....	34
7.1	Warning devices.....	34
7.2	Marking.....	34
7.2.1	General.....	34
7.2.2	Additional markings.....	34
7.3	Instruction handbook.....	35
7.3.1	General.....	35
7.3.2	Additional information.....	35
	Annex A (informative) List of significant hazards.....	38
	Annex B (informative) Performance level required.....	40
	Annex C (normative) Stability test.....	41
	Annex D (normative) Test for braking function.....	42
	Annex E (normative) Impact test for guards.....	43
	Annex F (normative) Noise test code.....	44
	Annex G (informative) Determination of maximum spindle speeds for single piece arbors.....	47
	Annex H (normative) Rigidity test for pressure pads, hand protectors and guiding steadies.....	51
	Bibliography.....	57