

# DIN EN 13035-6:2006-11 (E)

## Machines and plants for the manufacture, treatment and processing of flat glass - Safety requirements - Part 6: Machines for break out

---

<b>Contents</b>		<b>Page</b>
Foreword .....		3
Introduction .....		4
1 <b>Scope</b> .....		5
2 <b>Normative references</b> .....		5
3 <b>Terms and definitions</b> .....		6
4 <b>List of significant hazards</b> .....		7
5 <b>Safety requirements and/or protective measures</b> .....		9
6 <b>Verification of the safety requirements and/or protective measures</b> .....		11
7 <b>Information for use</b> .....		12
<b>Annex ZA (informative) Relationship between this European Standard and the Essential Requirements of EU Directive 98/37/EC</b> .....		<b>14</b>
<b>Bibliography</b> .....		<b>15</b>
<b>Tables Table 1 -- List of significant hazards</b> .....		<b>7</b>
<b>Table 2 -- Individual testing for requirements stated in Clause 5</b> .....		<b>11</b>