

# DIN ISO 29661:2016-11 (E)

## Reference radiation fields for radiation protection - Definitions and fundamental concepts (ISO 29661:2012)

---

Contents	Page
National foreword .....	4
National Annex NA (informative) Referenced documents and corresponding European and international documents .....	4
National Annex NB (informative) Bibliography .....	5
Introduction .....	6
1 Scope .....	6
2 Normative references .....	7
3 Terms and definitions .....	7
3.1 General .....	7
3.2 Quantities and conversion coefficients .....	17
4 Symbols .....	25
5 Application of the measurement quantities and units .....	28
5.1 Measurement quantities for area monitoring .....	28
5.2 Measurement quantities for individual monitoring .....	28
5.3 Establishing of the measurement quantities for area and individual monitoring .....	28
6 Calibration and determination of the response in reference radiation fields .....	29
6.1 General principles .....	29
6.1.1 Parts to be irradiated .....	29
6.1.2 Conditions of the dosimeter under test .....	29
6.1.3 Point of test and reference point .....	30
6.1.4 Axes of rotation .....	30
6.1.5 Reference conditions and standard test conditions for influence quantities .....	30
6.2 Calibration in reference radiation fields .....	30
6.2.1 Concept of calibration .....	30
6.2.2 Determination of the conventional quantity value from a secondary or a working standard .....	31
6.2.3 Determination of the corrected indicated value and the calibration coefficient .....	31
6.2.4 Determination of the measured value .....	32
6.3 Determination of the response in reference radiation fields .....	33
6.4 Methods for the determination of the calibration coefficient .....	33
6.4.1 Procedures .....	33
6.4.2 Sequential irradiation of standard and dosimeter .....	34
6.4.3 Simultaneous irradiation of standard and dosimeter .....	34
6.4.4 Calibration and determination of the response using a calibrated monitor device .....	36
6.4.5 Calibration and determination of the response using a reference radionuclide source unit .....	37
6.5 Special considerations for area dosimeters (area survey meters) .....	37
6.5.1 Reference point and reference direction .....	37
6.5.2 Irradiation conditions .....	38

<b>6.6</b>	<b>Special considerations for personal dosemeters.....</b>	<b>38</b>
<b>6.6.1</b>	<b>General .....</b>	<b>38</b>
<b>6.6.2</b>	<b>Phantoms.....</b>	<b>39</b>
<b>6.6.3</b>	<b>Reference direction and reference point.....</b>	<b>39</b>
<b>6.6.4</b>	<b>Irradiation conditions.....</b>	<b>40</b>
<b>6.6.5</b>	<b>Simultaneous irradiation of several dosemeters.....</b>	<b>41</b>
<b>7</b>	<b>Uncertainty .....</b>	<b>42</b>
<b>8</b>	<b>Certificates .....</b>	<b>42</b>
<b>Annex A (normative) List of reference conditions and standard test conditions .....</b>		<b>43</b>
<b>Annex B (normative) Description of the calibration coefficient .....</b>		<b>44</b>
<b>Bibliography .....</b>		<b>46</b>

## Bilder

<b>Figure 1 — Reference direction and direction of radiation incidence of personal dosimeter mounted on water slab phantom [see 6.6.2 a)].....</b>	<b>15</b>
<b>Figure 2 — Sketch of simultaneous irradiation of standard and dosimeter .....</b>	<b>35</b>
<b>Figure 3 — Positioning of whole-body dosimeter at slab phantom surface (reference direction normal to phantom surface) .....</b>	<b>41</b>

## Tabellen

<b>Table 1 — Symbols .....</b>	<b>25</b>
<b>Table A.1 — Reference conditions and standard test conditions.....</b>	<b>43</b>