

ISO 20553:2006-04 (E)

Radiation protection - Monitoring of workers occupationally exposed to a risk of internal contamination with radioactive material

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	2
3	Terms and definitions	2
3.1	Absorption types	2
4	Symbols and abbreviated terms	6
5	Purpose and need for monitoring programmes	6
6	Reference levels	8
7	Routine monitoring programmes	9
7.1	General aspects	9
7.2	Workplace monitoring	10
7.3	Individual monitoring	10
7.4	Methods and time intervals	11
8	Special monitoring programmes	14
8.1	General aspects	14
8.2	Workplace monitoring	14
8.3	Individual monitoring	15
9	Task-related monitoring programmes	17
9.1	General aspects	17
9.2	Workplace monitoring	17
9.3	Individual monitoring	17
10	Special cases of individual monitoring	18
10.1	Actinides	18
10.2	Contamination in wounds	18
10.3	Contamination on the skin	18
11	Recording, documentation and reporting	18
11.1	Recording and documentation	18
11.2	Reporting	20
12	Quality management	20
Bibliography		22