

DIN EN ISO 15011-2:2010-03 (E)

Health and safety in welding and allied processes - Laboratory method for sampling fume and gases - Part 2: Determination of the emission rates of carbon monoxide (CO), carbon dioxide (CO₂), nitrogen monoxide (NO) and nitrogen dioxide (NO₂) during arc welding, cutting and gouging (ISO 15011-2:2009)

Contents		Page
Foreword		3
Introduction		4
1 Scope		5
2 Normative references		5
3 Terms and definitions		5
4 Principle		6
5 Equipment and materials		6
6 Test procedures		8
6.1 Welding procedure selection		8
6.2 Setting up the test equipment		8
6.3 Blank test		9
6.4 Manual metal arc welding		9
6.5 Continuous wire processes and autogeneous TIG welding		9
6.6 Cutting and gouging		10
7 Calculating and reporting the results		11
Annex A (informative) Possible designs of hood		12
Annex B (informative) Equipment notes		14
Annex C (informative) Welding parameters for gas-shielded arc welding		16
Annex D (normative) Test procedures		19
Annex E (normative) Calculation of the average stable gas concentration		20
Annex F (normative) Test report		21
Bibliography		22