

DIN EN ISO 15011-1:2010-03 (E)

Health and safety in welding and allied processes - Laboratory method for sampling fume and gases - Part 1: Determination of fume emission rate during arc welding and collection of fume for analysis (ISO 15011-1:2009)

Contents	Page
Foreword	3
Introduction	4
1 Scope	5
2 Normative references	5
3 Terms and definitions	5
4 Principle	6
5 Equipment and materials	6
6 Tests procedures	7
6.1 Welding procedure selection	7
6.2 Manual metal arc welding	7
6.3 Continuous wire processes	9
6.4 Analysis of the fume collected	11
7 Calculating and reporting the results	11
Annex A (informative) Possible designs of test chamber	12
Annex B (informative) Equipment notes	18
Annex C (informative) Welding parameters	20
Annex D (normative) Test procedures	22
Annex E (normative) Test report	23
Bibliography	24