

# DIN EN ISO 15011-1:2010-03 (E)

Health and safety in welding and allied processes - Laboratory method for sampling fume and gases - Part 1: Determination of fume emission rate during arc welding and collection of fume for analysis (ISO 15011-1:2009)

---

<b>Contents</b>	<b>Page</b>
Foreword .....	3
Introduction .....	4
1 Scope .....	5
2 Normative references .....	5
3 Terms and definitions .....	5
4 Principle .....	6
5 Equipment and materials .....	6
6 Tests procedures .....	7
6.1 Welding procedure selection .....	7
6.2 Manual metal arc welding .....	7
6.3 Continuous wire processes .....	9
6.4 Analysis of the fume collected .....	11
7 Calculating and reporting the results .....	11
Annex A (informative) Possible designs of test chamber .....	12
Annex B (informative) Equipment notes .....	18
Annex C (informative) Welding parameters .....	20
Annex D (normative) Test procedures .....	22
Annex E (normative) Test report .....	23
Bibliography .....	24