

ISO 2553:1992-10 (E)

Welded, brazed and soldered joints - symbolic representation on drawings

Contents

Page

| | |
|---|----|
| 1 Scope | 1 |
| 2 Normative references | 1 |
| 3 General | 1 |
| 4 Symbols | 2 |
| 4.1 Elementary symbols..... | 2 |
| 4.2 Combinations of elementary symbols | 5 |
| 4.3 Supplementary symbols | 6 |
| 5 Position of the symbols on drawings..... | 8 |
| 5.1 General | 8 |
| 5.2 Relationship between the arrow line and the joint | 8 |
| 5.3 Position of the arrow line | 10 |
| 5.4 Position of the reference line | 10 |
| 5.5 Position of the symbol with regard to the reference line | 11 |
| 6 Dimensioning of welds | 12 |
| 6.1 General rules | 12 |
| 6.2 Main dimensions to be shown | 12 |
| 7 Complementary indications | 18 |
| 7.1 Peripheral welds | 18 |
| 7.2 Field or site welds | 18 |
| 7.3 Indication of the welding process | 18 |
| 7.4 Sequence of information in the tail of the reference mark | 18 |
| 8 Examples for application of spot and seam joints | 19 |
| | |
| Annexes | |
| | |
| A Examples of use of symbols | 22 |
| B Guidance for converting drawings made in accordance with ISO 2553:1974 into the new system in accordance with ISO 2553:1991..... | 50 |